By Jan Axelson ACCESS SERIAL PORTS WITH VISUAL BASIC .NET



If you have a microcontroller circuit that needs to talk to a PC, a serial port can do the job. Serial ports can transfer data for just about any purpose. For example, a microcontroller can send sensor data for a PC to analyze and display. Or, a PC can send commands to control robots or other devices.


No serial port on your PC? No problem! To add a serial port, attach a USB/serial adapter to a USB port. This article focuses on the PC side of serial port communications. I'll show how to use Visual Basic .NET to access serial ports, including USB virtual serial ports.

Serial Ports and COM Ports

A serial port is a computer interface that transmits bits one at a time. The interface can have as few as three lines: one to carry data in each direction plus a ground line. Many interfaces have up to six additional lines to carry status and control information.

Unlike some serial interfaces, the standard RS-232 serial interface on PCs doesn't include a clock line. Instead, the computers at both ends of the cable each provide a clock. The computers must agree on a bit rate for transferring data, and a Start bit synchronizes the clocks before each transmitted byte.

RS-232 is a hardware interface that transmits 0s and 1s as positive and negative voltages. A typical RS-232 cable can be up to 100 ft long. Interface chips such as Maxim's MAX232 converts between 5V logic and RS-232 voltages.



On a PC, serial ports appear as numbered COM ports that applications can read and write to. These days, most standard peripherals connect via USB, and many PCs don't have built-in serial ports. You can add an RS-232 port to any recent PC, however, by attaching a USB/RS-232 adapter module. Your favorite PC hardware vendor likely has a selection to choose from.

tł P

St

th Tc ro

ar

or

ne

Th

Th

pa Th

pr (Fo

rai

an

ch

of

th

W

op

wi

op

wi

ca

rea

mi

op pr

op

For each adapter, Windows creates a USB virtual COM port that applications can access just like built-in serial ports. If you don't want to use an external adapter, you can perform the conversion inside the device by adding a USB/serial bridge chip to your design. FTDI's FT232R is an example of a bridge chip.

Selecting a Port

Figure 1 shows a Windows form for an application that uses a serial port to control an LED on a remote device. (The full Visual Basic project is available from **www.nutsvolts.com** and my website, **www.Lvr.com**.)

Combo boxes enable selecting a COM port and bit rate. Clicking the ON or OFF button sends a command to turn an LED on the remote device on or off. A label displays a message about the state of the LED as

reported by the device.

This example can serve as a framework for developing applications that monitor and control other external devices.

Microsoft's Visual Basic .NET, including the free Express edition, includes a SerialPort class for accessing COM ports. Other .NET languages such as Visual C# can use the class, as well.

FIGURE 1. Clicking a button sends a command and displays a response.

60 NUTS VOLTS April 2008

In applications that use the SerialPort class, include imports statement to avoid having to specify the namespace each time you use a class member. Place the statement at the top of the file, preceding the Module or Class statement and following any Option statements:

Imports System. IO. Ports

Before you can access a port, you need to create a SerialPort object. This statement creates a SerialPort object called myComPort:

Dim myComPort As New SerialPort

Listing 1 shows a routine that finds COM ports on the system and sets a default port and other parameters. To run the routine when the application starts, call the routine in the Form_Load event.

The SerialPort class's GetPortNames method returns an array of the names of all of the PC's COM ports. The array's elements aren't guaranteed to be in alphabetical order, but the Array.Sort method can sort the names if needed. The SelectedIndex property sets the default COM port.

The cmbPorts combo box displays the COM ports.

cmbBitRate combo box lists the supported bit rates.

SelectedItem property sets the default bit rate.

Accessing a Port

The OpenComPort routine (Listing 2) sets port parameters and attempts to open the selected port. The routine sets myComPort's PortName and BaudRate properties to match the selections in the combo boxes. (For the purposes of this discussion, the bit rate and baud rate are the same thing.)

For other properties such as the number of data bits and parity type, the routine sets values. To enable users to change these properties, you can add combo boxes that offer options for these properties.

The ReadTimeout and WriteTimeout values set the number of milliseconds the application will wait when attempting to read or write to the port. For read operations, the timeout sets how long the application will wait for data after calling a read method. For write operations, the timeout sets how long the application will wait to finish a write operation. Flow-control methods can delay writing to a port if the receiving computer isn't ready to accept data.

Before reading or writing to a port, the application must open a connection to the port. The Open method pens a connection to the port named in the PortName operty. If the selected port doesn't exist, is already open, or can't be opened for another reason, a message

box appears describing the problem.

The CloseComPort routine (Listing 3) closes an open port and releases its resources. The form's FormClosing event can call this routine to close the port when the application ends. The routine waits for any transmitting bytes to finish transmitting or a timeout. The Using block's End Using statement closes myComPort and disposes of its resources.

Closing a port can take up to a few seconds, so applications and users should delay a bit between closing a port and re-opening the same one.

When a user selects a new COM port in the cmbPorts combo box, the combo box's SelectedIndexChanged event executes. Placing this code in the event's routine closes the previously selected COM port if needed, sets myComPort's PortName

Sub InitializeForm()

Dim bitRates(9) As Integer Dim nameArray() As String LISTING 1. Combo boxes on the form enable users to select a port and bit rate.

' Find the COM ports on the system.

nameArray = SerialPort.GetPortNames
Array.Sort(nameArray)

' Fill a combo box with the port names.

' Select a default port.

cmbPorts.SelectedIndex = 1

'Bit rates to select from.

bitRates(0) = 300

bitRates(1) = 600

bitRates(2) = 1200

bitRates(3) = 2400

bitRates(4) = 9600

bitRates(5) = 14400

bitRates(6) = 19200

bitRates(7) = 38400

bitRates(8) = 57600

bitRates(9) = 115200

'Place the bit rates in a combo box.

' Select a default bit rate.

cmbBitRate.SelectedItem = 1200

End Sub

Sub OpenComPort() Try ' Get the selected COM port's name ' from the combo box. If Not myComPort.IsOpen Then myComPort.PortName = cmbPorts.SelectedItem.ToString ' Get the selected bit rate from the combo box. If cmbBitRate.SelectedIndex > 0 Then myComPort.BaudRate = CInt (cmbBitRate.SelectedItem) End If ' Set other port parameters. myComPort.Parity = Parity.None myComPort.DataBits = 8 myComPort.StopBits = StopBits.One myComPort.Handshake = Handshake.None myComPort.ReadTimeout = 3000 myComPort.WriteTimeout = 5000 ' Open the port. myComPort.Open() End If Catch ex As InvalidOperationException MessageBox.Show(ex.Message) Catch ex As UnauthorizedAccessException MessageBox.Show(ex.Message) Catch ex As System. IO. IOException MessageBox.Show(ex.Message) LISTING 2. Before transferring End Try data, the application must set port parameters and open a End Sub connection to the port.

Sub CloseComPort()

Using myComPort

If (Not (myComPort Is Nothing)) Then

' The COM port exists.

If myComPort.IsOpen Then

' Wait for the transmit buffer to empty.

Do While (myComPort.BytesToWrite > 0)
Loop

End If
End If
End If
End Using

LISTING 3. The End Using statement closes the port and

disposes of its resources.

property to match the new selected port, and opens the selected port:

CloseComPort()
myComPort.PortName = _
 cmbPorts.SelectedItem.ToString
OpenComPort()

When a user selects a new bit rate in the cmbBitRate combo box, the combo box's SelectedIndexChanged event executes. Placing this code in the event's routine sets myComPort's BaudRate property to match the selected bit rate:

myComPort.BaudRate = __
CInt(cmbBitRate.SelectedItem)

Each button on the form has a click event, which calls the SendCommand routine to send a command to the COM port. Place this code in the ON button's click event to send the command "L11":

n

in

E>

CO

de

in

00

de

th

an

30

re

let

us

en

les

sa

se

be

da

SendCommand ("L11")

The first two bytes ("L1") identify LED 1 on the device. The third byte "1" tells the device to turn on LED 1.

Place this code in the OFF button's click event to send "L10" to tell the device to turn off LED 1:

SendCommand("L10")

Listing 4 is the SendCommand routine. The WriteLine method writes the command and a line-feed (LF) code (0Ah) to the port. Using the SerialPort class's default encoding, each text character transmits as an eight-bit ASCII code.

The application waits to receive a response that ends with an LF. On receiving a response, a label on the form (lblStatus) displays a message. If the device doesn't respond after the number of milliseconds in ReadTimeout, a message box displays an error message.

You can request other actions from the remote device by modifying or adding to the commands and responses. To automate the communications, a Timer component's Tick event can send commands at intervals.

Detecting Received Data

In the example application, the device sends data only when the PC application requests it. If your device sends data at unpredictable times, the DataReceived event can detect data when it arrives.

End Sub

Listing 5 shows how to use the event to retrieve ata. The SerialPort class's DataReceived code runs in a different program thread. For this reason, if you retrieve received data in a DataReceived event and want to display the data on the application's form, you need to define a delegate to pass the data to the form. For an example of how to do so, see the ComPortTerminal example at www.Lvr.com.

Another way to detect received data is to use a Timer component to check for new data at intervals.

More on Transferring Text

The example application sends and receives data — including numbers — as codes that represent text characters. For example, to send "1," the port transmits the byte 31h (00110001), which is the ASCII code for the character 1. To send "111," the port transmits 31h three times; once for each character in the number.

Treating data as text is the obvious choice for transferring strings or files that contain text. To transfer numeric values, one option is to send the bytes as text in ASCII hex format.

Any byte value can be expressed as a pair of hexadecimal (base 16) characters where the letters A-F represent values from 10 to 15.

For example, consider the decimal number 225. xpressed as a binary value, it's (2^7) + (2^6) +(2^5) +(2^0), or: 11100001. In hexadecimal, it's E1. The ASCII codes for the characters "E" and "1" expressed in hexadecimal are: 45 31. So the binary representation of E1h in ASCII hex consists of these two bytes: 01000101 00110001.

A serial link using ASCII hex format sends the decimal value 225 by transmitting the two bytes above. A computer that receives ASCII hex values can convert the characters to numeric values or use the data as-is.

An advantage to ASCII hex is being able to represent any byte value using just 16 ASCII codes. The values 30h-39h represent the characters 0-9, and 41h-46h represent the characters A-F. Code that allows lower-case letters uses 61h-66h to represent a-f.

All of the other values are available for alternate uses, such as software flow-control codes or an end-of-file indicator. Because the ASCII hex codes are all less than 80h, a serial link transmitting these values can save a little time by ignoring the high bit and transmitting seven-bit values.

Listing 6 shows Visual Basic functions for converting between binary values and ASCII hex strings.

Listing 4 used WriteLine and ReadLine to exchange data. The SerialPort class provides several other options

for reading and writing text. To send a string without appending an LF, use the Write method. The Write method can also write a Char array to a port. The

Private Sub SendCommand (ByVal command As String)

Dim response As String

Try

myComPort.WriteLine(command)
response = myComPort.ReadLine

Select Case response

Case "0"

lblStatus.Text = "LED 1 is OFF"

Case "1"

lblStatus.Text = "LED 1 is ON"

Case Else

End Select

Catch ex As TimeoutException
MessageBox.Show(ex.Message)

Catch ex As InvalidOperationException
MessageBox.Show(ex.Message)

Catch ex As UnauthorizedAccessException MessageBox.Show(ex.Message)

End Try

End Sub

LISTING 4. The SendCommand routine sends a text command to the COM port and waits for a response.

Define the event handler for received data.

Private SerialDataReceivedEventHandler1 _
As New SerialDataReceivedEventHandler _
(AddressOf DataReceived)

- ' Specify the routine that runs when
- ' a DataReceived event occurs at myComPort.

AddHandler myComPort.DataReceived, _ SerialDataReceivedEventHandler1

' This routine runs when data arrives at myComPort.

Friend Sub DataReceived(ByVal sender As Object, _ ByVal e As SerialDataReceivedEventArgs)

Dim newReceivedData As String

' Get data from the COM port.

newReceivedData = myComPort.ReadExisting

Console.WriteLine(newReceivedData)

End Sub

LISTING 5. The DataReceived event can detect and retrieve received data.

Private Function ConvertAsciiHexToByte _
(ByVal asciiHexToConvert As String) As Byte

Dim convertedValue As Byte

convertedValue = Convert.ToByte(asciiHexToConvert, 16)
Return convertedValue

End Function

Private Function ConvertByteToAsciiHex _
(ByVal byteToConvert As Byte) As String

Dim convertedValue As String

convertedValue = Hex\$(byteToConvert)
Return convertedValue

End Function

LISTING 6. These functions convert between byte values and ASCII hex strings that represent the bytes.

ReadExisting method in Listing 5 returns immediately with everything in the receive buffer or an empty string if the buffer is empty. The ReadTo method is like ReadLine but enables defining any character as the delimiter. The Read method copies received characters into a Char array.

If those options aren't enough, you can use the SerialPort object's BaseStream property to obtain a Stream object for transferring text data. For more on any of these methods, see .NET's Help.

Transferring Binary Data

A disadvantage of using ASCII for numeric data is that each byte value uses two characters, so data takes twice as long to transfer. Also, in most cases the application at each end must convert between hex and binary.

With binary data, values aren't converted to text characters. The decimal value 1 transmits as 00000001 rather than as the ASCII code for the character "1." With binary data, any value from 0 to 255 can transmit as a single byte. When sending or receiving binary data, the SerialPort object assumes nothing about what the values mean.

A way to transmit binary data is to place the bytes in an array. This example creates a three-byte array and writes the array's contents to a port:

Dim byteBuffer(2) As Byte

byteBuffer(0) = 85

byteBuffer(1) = 83

byteBuffer(2) = 66

myComPort.Write(byteBuffer, 0, 3)

Sources

Future Technology Devices International
Limited (FTDI)
USB/serial bridge chips
www.ftdichip.com

Maxim Integrated Products
RS-232 and RS-485 interface chips
www.maxim-ic.com

Microsoft
Visual Basic Express Edition
www.microsoft.com/express/vb

The SerialPort class provides two methods for reading bytes. The Read method can copy a specified number of received bytes from the receive buffer into a byte array beginning at a specified offset.

This example reads up to three received bytes, stores the bytes beginning at offset 0 in the byteBuffer array, and displays the result:

Dim byteBuffer() As Byte = $\{0, 0, 0\}$

myComPort.Read(byteBuffer, 0, 3)

The Read method doesn't wait for the specified number of bytes to arrive but returns when there is at least one received byte. If no bytes arrive, the method times out when the ReadTimeout time has elapsed.

Another option for reading bytes is the ReadByte method, which reads one byte at a time:

Dim receivedByte As Integer

receivedByte = myComPort.ReadByte

The ReadByte method reads a byte but returns an Integer with its high bytes set to zero. As with text data, Stream objects are another option for transferring binary data.

Moving On

Next time, we'll look at serial communications for microcontrollers. I'll show how to program a PIC microcontroller to detect and respond to commands received over a serial port. **NV**

Contact the Author

Jan Axelson is the author of Serial Port Complete, now in its second edition. Jan's website is www.Lvr.com.